



Use 5/16 mill bit to cut slots with gear clamped in vise.

First drill the inside diameter to size on lathe and then center the gear in vise on mill.



DRAWN
BSR

6/10/2005