








Note, on this package, the big lead is vout too. Connect it in.



Power filter capacitor for the motor. Should it be larger?



MA, MB, MCOAST, and MENABLE are the control lines.



Wire bus8 into controller.

Just solder this cap across the input terminals.

